
## NOTES:

- 1. Meters must be installed in horizontal position only.
- 2. The meter must be in a location such that the meter is <u>serviceable</u>.
- 3. All piping and meters must be property hung and supported.



----- Iron Size Brass pipe and fittings

cubic feet) with 15 foot factory pre-wired lead, or Hersey Systems 400 Series Magnetic Drive Positive, Displacement The three types of meters that are available are: NEPTUNE T-10(in cubic feet), Zenner Multi-Jet Encoder Meter (in The City of Newton requires all outdoor meters to be 3/4" and capable to work with the existing KP meter system. Disc Meter